




CUSTOMER IS RESPONSIBLE FOR DETERMINING THAT BALDOR'S PRODUCT WILL PERFORM SUITABLY IN THE INTENDED APPLICATION.

REV. DESC: CORRECT LEADER TO SAY 5.88 DIA B.C.

REV. LTR: A

VERSION: 01

TDR: 000000778254

FILE: \AAA\00173\887

REVISED: 01: 44:13 12/18/2012

MTL: -

BY: ENJESMO

BALDOR

STD HORZ 143-5TC TEFC 35M W/ 1.09 DIA. LEAD HOLE

SH 1 of 1