





CUSTOMER IS RESPONSIBLE FOR DETERMINING THAT BALDOR'S PRODUCT WILL PERFORM SUITABLY IN THE INTENDED APPLICATION.

REV. DESC: CORRECTED LOCATION OF FAN HOUSE

REV. LTR: L

VERSION: 01

TDR: 00000882490

FILE: \AAA\00004\168

REVISED: 01:11:39 12/01/2014

BY: ENCHALO

MTL: -



**BALDOR**

STD HORZ 182-4JP TEFC 36M

SH 1 of 1