





CUSTOMER IS RESPONSIBLE FOR DETERMINING THAT MOTOR PERFORMANCE IS SUITABLE IN THE APPLICATION.

REV. DESC: MOVED LEADER TO POINT TO CORRECT 4 HOLES

REV. LTR: M BY: YD REVISED: 02/23/01 8:46 TDR: 0232850

34LY6242

FILE: AAA00021369

REF: -

MTL: -

BALDOR ELECTRIC Co.

STD HORZ MODEL 34 PM TEFC IEC D71C-B14 2 POLE W/M.F.T.K.