


AERATION FAN MOTOR

CUSTOMER IS RESPONSIBLE FOR DETERMINING THAT MOTOR PERFORMANCE IS SUITABLE IN THE APPLICATION.

REV. DESC: LEAD HOLE .88 DIA WAS LEAD HOLE .88 DIA. W/PLUG

REV. LTR: A

VERSION: 01

TDR: 000000444235

8061A792

FILE: \AAA\00110\931

REVISED: 21:15:40 09/24/2007

MTL: -

BY: ENMARHO

BALDOR ELECTRIC Co.

HOR 143-5T TEAO 35M-T.P/AERA FAN, 2 POLE "W" BASE(35BA4009)