


33E887-0673G2



CUSTOMER IS RESPONSIBLE FOR DETERMINING THAT BALDOR'S PRODUCT WILL PERFORM SUITABLY IN THE INTENDED APPLICATION

REV. DESC: NEW

REV: - VERSION: 00

REVISED: 09:40:19 11/13/2015

TDR: 000000951888

33E887-0673G2

MODEL NO. 33E887-0673G2


REF:

BY: CKYUKP0


BALDOR

LY,33AC PSL RSB TEFC 2.00 X 0.75 KEY


33E887-0673G2



SECTION R-R



SECTION B-B



CUSTOMER IS RESPONSIBLE FOR DETERMINING THAT BALDOR'S PRODUCT WILL PERFORM SUITABLY IN THE INTENDED APPLICATION

REV. DESC: NEW			
REV: -	VERSION: 00	REVISED: 09:40:19 11/13/2015	TDR: 000000951888
33E887-0673G2		MODEL NO. 33E887-0673G2	REF:
		BY: CKYUKP0	

BALDOR

LY,33AC PSL RSB TEFC 2.00 X 0.75 KEY

33E887-0673G2

ITEM NO.	PART NUMBER	QTY.
1	HG0076A16	1
2	BMH1714	2
3	BH1165A02	1
4	HW5002A95	1
5	HW4600D35	1
6	BH1163A02	1
7	HA4021A05	1
8	HW3064E05	1
9	33SH7271B01	1
10	33RC4120-00	1
11	BG6203C03	1
12	33SA9200B96	1
13	NS2512A01	1
14	34GS1029A01	1
15	34CB3002C	1
16	51XB1016A07	2
17	11XT1032G06	1
18	34CB4517	1
19	34GS1031A01	1
20	51XT0832A07	4
21	33EP3100A01	1
22	HW5109A05	1
23	HA3100A	2
24	33FN3000	1
25	12XN0832A16	1
26	HW1003A08	1
27	XY0832A02	1
28	33FH4000A01	1
29	51XB1016A06	3
30	SG0045C11	1
31	SG0045C12	1
32	SG0045C13	1
33	CG0012A01	1
34	RM1020A22	1
35	BH1163A03	1
36	HW4600D39	1
37	60XM2520A12	4
38	LC0005	1
39	LB1119	1
40	BMH1910	1
41	HA4067	2
42	NP1220A 33AC RSB	1

CUSTOMER IS RESPONSIBLE FOR DETERMINING THAT BALDOR'S PRODUCT WILL PERFORM SUITABLY IN THE INTENDED APPLICATION

REV. DESC: NEW

REV: - VERSION: 00 REVISED: 09:40:19 11/13/2015 TDR: 000000951888

33E887-0673G2

MODEL NO. 33E887-0673G2


BY: CKYUKP0

REF:

BALDOR

LY,33AC PSL RSB TEFC 2.00 X 0.75 KEY

33E887-0673G2



33E887-0673G2